



2010 43QGP Allegro Bus

5/8/2011

6 – FYI - AQUA-HOT ELECTRONIC PANEL CONNECTIONS.

The one purpose for this FYI is to inform owners of an Aqua-Hot system of a potential problem which may affect your unit. On my unit the Tiffin worker did not properly secure the JP2 connector on the Aqua-Hot's electronic control panel. The only reason other than lazy I can think of is after installing the four screws which mount the control panel on the white back board the installer did not have a short screw driver to properly secure the JP2 connector screws to the control panel. The JP connectors JP1 through JP4 are mated with board mounted JP1 through JP4 connectors. At the top and bottom of each connector are small screws which are designed to be screwed into the board mounted connector. The JP2 connector was mated with the board mounted connector however the screws were not tightened. As already stated I believe the Tiffin employee did not have a screwdriver short enough to properly complete the installation, so the connector was just pushed on and left.

IMO, the JP2 connector **CAN** if not properly secured eject itself from its board mounted mate connector.

