



## 2010 43QGP Allegro Bus

2/21/2012

**41 – FYI - TIFFIN CHASSIS BARE METAL.** We have owned two Tiffin coaches both coaches were shipped with more bare chassis metal then I thought was possible. It appears when the chassis painter is painting the chassis if the metal cannot be seen from a standing position it does not get painted. I lost count how many cans of spray paint have been used on the chassis metal of our two coaches. While working on another modification more bare metal was found which had not been painted on the firewall.



I understand some wiring is installed in the welding shop prior to the chassis being painted. But you can see in the above firewall photograph MOST of this wiring had been installed BEFORE the chassis had been undercoated or painted. The lower section of the firewall just above the generator had not been painted from side to side, also the bottom of the firewall had not been

painted either. Painting both firewall sections (face and bottom) POST production was not easy.



Rubber coated straps and tie wraps re-installed after firewall bare metal had been painted and installation of Crusingator's Modification # 50 - Dash AC Condensate Diverter had been installed.