

## 2010 43QGP Allegro Bus

## 8/14/2012

**58 – FYI – OPERATION OF KEY FOB & KEY PAD.** Tiffin installed an electric locking/un-locking system on the entry door and **MOST** cargo doors. Our coach has three Driver Side and three Passenger Side cargo doors which do not have electric locks those six cargo doors require a key to lock or unlock. Using the Tri-Mark Manual supplied with our coach and testing the various features led me to the following conclusions based on observations.

- 1. Tiffin **DID NOT** wire our coach with a security system.
- 2. Tiffin **DID NOT** wire the horn to the Tri-Mark system.
- 3. Tiffin **DID** wire the headlights and front side marker lights.

## **KEY FOB OPERATION:**

LOCK ENTRY DOOR: One flash of both headlights and front side marker lights.

UNLOCK ENTRY DOOR: Patio and Door lights turn ON for 60 seconds.

LOCK CARGO DOORS: One flash of both headlights and front side marker lights.

UN-LOCK CARGO DOORS: No operation

## **DOOR KEY PAD OPERTION:**

TO **UNLOCK** requires a FIVE digit ACCESS CODE + (PLUS) one of the following numbered keys.

1/2 > UNLOCKS THE ENTRY DOOR

- 3/4 > UNLOCKS CARGO DOORS & ENTRY DOOR Headlights Flash Twice.
- 5/6 > NO FUNCTON

7/8 > UNLOCKS CARGO DOORS

9/0 > NO FUNCTION

TO LOCK ALL ELECTRIC CARGO DOORS & ENTRY DOOR, depress the 1/2 Key Pad and hold until you hear the doors lock, <u>NO ACCESS CODE NEEDED</u>.

NONE of the other Tri-Mark Functions are wired to operate on our coach!