

## 2010 43QGP Allegro Bus

## 5/1/2014

ONE-HUNDRED-FIFTH - coach modification – <u>NEW DRIVING</u> <u>LIGHTS.</u> After fighting a water leak on the passenger side driving light for three plus years I gave up last week. Every time we drove in the rain the driving lights would fog up with a little with water in the glass envelope after a few days without rain the glass envelope would clear. We decided to purchase a set of 55 watt driving lights from Walmart for a little under \$ 20.00 including tax. The new lights are 3 ½ inches in diameter where the Tiffin OEM lights were a little smaller at 3 inches. The new lights fit in the five inch recessed hole without any problems.



As I have aged driving at night has gotten to be less fun, too may road gators get left behind by too many trucks. At night, driving my normal 60 MPH it is too easy to run over one of those black spots in the road. It is my opinion the more light I can put on the road the better.