




2010 43QGP Allegro Bus

5/8/2011

7 – FYI - **WINDOW AWNING FABRIC QUICK REPAIR.** While working on the coach and making a punch list for our next Tiffin warranty appointment I found all three of our window awnings had one end of the fabric pulling out of the metal cover. This after thinking for a few minutes was an item which I could see the Tiffin service personnel screwing up royally so I jumped in with both feet to find a DIY repair. I decided to use a small 3/16 inch hardwood dowel as the repair material as that was what I had in hand and I did not want to try tracking down any 3/16 inch plastic rod.



Remove the hex screw push the fabric loop back into the metal cover insert a piece of 3/16 inch dowel (cut the dowel length to fit inside the fabric loop) reinstall the hex screw and the repair has been completed.