




2010 43QGP Allegro Bus

1/27/2012

36 – FYI – CLEANING THE SLIDE END WINDOW. As a result of a thread on the TRVN forum, I checked the window on our Allegro Bus. We have one small window in the driver side slide and two of the same windows installed on both sides of our bed which is located on the bed slide.


I found as others have posted the screen cannot be removed without removing the window's inside trim. I do not think removing the trim is a safe method to clean the window. So after thinking the situation over this is what I decided to do. I removed the two window stops screwed into the window track. After the stops are removed the window can be raised high enough to allow cleaning the entire inside of the window without removing the screen.



The window clip used to hold the window open is mounted on the right side of the frame. The window clip must be held back so the window can be raised past and above the clip.



As seen in the below photo the window can be raised enough with the two rubber stops removed to allow accessing the entire inside of the slide window for cleaning.



The above allows access for easy window cleaning on our 2010 Allegro Bus.