



2010 43QGP Allegro Bus

4/3/2012

48 – FYI - TAG AND DRIVE AXLE HUB OIL SEALS. During our last visit to Red Bay another owner pointed out this problem to me. I should have spotted this myself however my plate has been full during the past three weeks while we vacationed in Red Bay. He pointed to my tag axle hub and stated I needed to have it checked. Yes, I did but first I took a good look at the other three drive and tag axle seals. As it turns out two hub seals were leaking, one drive axle hub and one tag axle hub.

Fortunately we were headed for the mechanical bays as our next stop. When we got to bay 43, I pointed out the problem to Kyle he proceeded to check all four of the hubs and seals. Below is a photo of our tag axle hub.



Notice two hub bolts are missing! They were completely missing they were not even contained inside the wheel hub. Makes me wonder about things?