

2010 43QGP Allegro Bus

4/28/2011

TWENTY-FIRST - coach modification, <u>PAINTING THE HWH</u>
<u>LEVELING COMPARTMENT</u>. We have used over one dozen spray cans of black paint in covering bare metal that had not been painted by Tiffin.



Above picture was **ONLY** part of the bare metal in this compartment. Below picture, after painting, yes it is now all painted black. I saw no sense adding another page just to display a larger **BLACK** picture.

