



2010 43QGP Allegro Bus

9/27/2012

SIXTY-SEVENTH - coach modification – **NEW BEDROOM WALL ART**. Our coach had the same bedroom wall art mounted on the rear bedroom wall as every other 2010 Allegro Bus or at least the 43QGP's. The two pieces of **ART** mounted on the wall created a hazard for me every time I tried to climb into or out of the bed. The two pieces of wall art projected more than an inch and closer to an inch and a half away from the wall which usually placed it in my path to the bed or out of the bed. I was constantly catching my clothes on the corner of one of the pieces.



After almost a year of looking for replacement wall art we were able to find a couple of metal art pieces in a Hobby Lobby in Nashville, Tennessee that met our specifications. The new art would not project far away from the wall, they would install in place of the original Tiffin Wall Art. They would

cover the holes in the wall from the OEM wall art and have a pleasing earth tone color.

The new art pieces after mounting project about 3/8" from the wall, leaving me about one inch more space to slide thru between the bed and wall than I had with the old wall art. Since the new wall art has been installed I have not YET gotten any of my clothing snagged on the new art pieces.

