


2010 43QGP Allegro Bus

2/14/2014

NINETY-EIGHTH coach modification **DOOR STEP MUD FLAP.**This photo shows the Tiffin installed guard to prevent mud and other debris from getting on the steps, the guard is show inside the **GREEN** box.



Step areas open to mud and debris are shown in **RED** above and below.

